



### NOTICE TO ALL FIRMS

Date: April 23, 2025  
To: All Prospective Bidders  
From: Sam Li  
Director of Procurement Services  
Re: Addendum Number 1  
IFB # C1686 – Alumni Hall Exhaust Riser Repairs Line D & E

#### Questions

- Q1. Regarding the air leakage test on each riser:  
Can we follow our standard procedures for this type of work? as follows:
1. Demo old diffusers in each are for entire riser
  2. Cap each vent openings in the space and EF fan on roof.
  3. Pressure test
  4. Remove caps
  5. Submit report before continue work, If the pressure test results are out of range, additional shaft inspection will be required and consult on how to move forward, based on concealed existing conditions.
- A1. The contractor should refer to the following: See note 1, 2 & 3 on DWG M-101 & spec section 23 05 67 Duct Cleaning. Contractor should provide visual inspection pre & post cleaning of the entire duct riser using a video camera. Submit for EOR review.

**THIS ADDENDUM IS PART OF THE CONTRACT DOCUMENT AND SHALL BE INCLUDED WITH YOUR REQUEST FOR PROPOSAL SUBMITTAL. YOUR SIGNATURE BELOW WARRANTS THAT YOU UNDERSTAND THIS ADDENDUM AND THAT YOU HAVE MADE THE APPROPRIATE ADJUSTMENTS IN YOUR PROPOSAL AND CALCULATIONS.**

\_\_\_\_\_  
Signature

\_\_\_\_\_  
Print Name and Title of Authorized Representative

\_\_\_\_\_  
Print Name of Company/Partnership/Individual

\_\_\_\_\_  
Date